Work Orde August 4, 2010		005				 		,			Page
Item ID: Revision ID:	D4148-5		· .	Accept				s	etup Start		
Item Name:	Eyebolt Stud					1 .			Stop		
Start Date: Required Date:	8/04/10 8/11/10	Start Qty: 10.00 Req'd Qty: 10.00	() = 0 () () () () () () ()	 I	Cust Item Customer	ł		,			ï
Reference:						<u> </u>		,	Store	.	111 1 1 0 1 1101 1 03 1
Approvals:	Process Pla	n:	Date: <u>///-//</u> // Date:	Tooling: SPC (Y/N):		Date:		R	tun Start Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr)					•	,
D4148	В										
100 Doosan		Memo		0.00	í		'				4 4
Doosan Lathe		turn as pe DWG RE	r dwg and folio FA951 V: 5 EV: N/A		L 10/08/10	≥ &		10			
		DEBURE	t		!						
		QC2- Inspect parts of	f machine FAI/FAIB	0.00	SL 10/08	108					
QC Quality Control	•	Memo		0.00							

W/O:			V	ORK ORDER CHAN	GES		İ			,
DATE	STEP	PRO	OCEDURE CH	ANGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			, , , , , , , , , , , , , , , , , , , 						Frod Wigi	
	<u> </u>									
	· · · · · · · · · · · · · · · · · · ·								-	
									<u>. </u>	
Part No		PAR #:	Fault Ca	tegory:	NCR:	Yes N	lo DQ A	:	_ Date: _	
	R	esolution:	Disposit	ion:	QA: N	C Clo	sed:		Date: _	
NCR:			WORK OR	DER NON-CONFORM	IANCE (I	ICR)				
DATE	STEP	Description of NC	In tal al		ection B	ign &	Verifica		Approval	Approval
	0	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section	C	Chief Eng	QC Inspector
								1		
								1		

Work Order ID 61005



Page 2

August 4, 2010 8:54:49 AM

Item]	ID:
--------	-----

D4148-5

Revision ID:

Eyebolt Stud Item Name:

Start Date:

8/04/10

Required Date: 8/11/10

Start Qty: 10.00 Req'd Qty: 10.00



Accept

Setup Start



Stop

Reference:

Approvals:

Process Plan:

Date: Tooling:

Date: SPC (Y/N):

0.00

0.00

Date:

Date:

Cust Item ID:

Customer':

Tool ID

Start Run

Stop

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC: ____

QC8- Inspect parts - second check

Memo

Identify as per dwg & Stock Location: 123

Set Up/ **Run Hours**

Tool # Plan Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

150

Packaging Packaging

Memo

0.00

0.00

160

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/08/10 10 mg

W/O:			V	ORK ORDER CHANG	ES		1			1
DATE	STEP	PROG	CEDURE CH	ANGE	B	y	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					1					
Part No		PAR #:					1			
	R	esolution:							Date: _	
NCR:		W	ORK OR	DER NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC			ion B	0	Verifica		Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	5	gn & Date	Sectio	С	Chief Eng	QC Inspector
										:
										•
								1		
								1		
								1		
								1		
	!							1		

Picklist Print

August 4, 2010 8:54:54 AM

Work Order ID: 61005

Parent Item: D4148-5

Parent Item Name: Eyebolt Stud



Start Date: 8/04/10

Required Date: 8/11/10

Page 1

Start Qty: 10.00

Required Qty: 10.00

Comments:

IPP REV:A NEW ISSUE 10-07-22 JLM VERIFIED BY:DD

M303R1.000 Purchased No f 14.2560 0.2 2.105263	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
			Purchased	No			f	14.2560	0.2	2.105263			

 Location
 Loc Otv
 Loc Code

 MAT028
 14.256
 113325

 113325
 14.256
 113325

- 2.2 JL 16/08/08

Dari Ae	rospace	Lia							•
W/O:			WO	RK ORDER CHANGE	S				,
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,									
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	lo DQA		_ Date: _	
	R	esolution:	Disposition	າ:	QA: N/C Clo	sed:		Date:	· · · · · · · · · · · · · · · · · · ·
NCR:		. \	WORK ORDE	ER NON-CONFORMA	NCE (NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
				<u> </u>					
							-		
							1		


DART AEROSPACE LTD	Work Order:	6/005
Description: eye bolt stud	Part Number:	D4148-5
Inspection Dwg: 1941-18 Rev: 18		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0 191	4.005	191	/			
1.38	+ .030	1.381	/			
(-060	010	.060				
.88	+ .030	879	//			
0.266	+-006 010	267				
-700	010	.696				
.230×415°	±-010 ±.5°	235X45		 		
350	+.010	1-2-				
.310	± .010	1.727				
1,725	± .010	124				
100	± .030	100			·	
750	-,030	.747				
735	+.010	737	/			
			-			
			+			
		-				

		119		
Measured by:	51	Audited by:	Preliminary Approval:	
		Date: 15/28/0	Date:	
Date:	10/08/08	Bate. 15/00/0	7	


Pou	Date	Change	Revised by	Approved
Rev		A 1.1 / Maria and an acceptable	KJ	




W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•	:					
Part No	:	PAR #:	Fault Cate	egory:	_ NCI	R: Yes	No DQA :		_ Date: _	
_	R	esolution:	Disposition	on:	_ QA	N/C Clo	sed:	!	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action Section	on B	0: 0	Verifica	ton	Approval	Approval
	0121	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
		·								
W										




W/O:	ļ		VVC	ORK ORDER CHANG	E9				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA :		Date:	
	R	esolution:	Disposition	n:	_ QA: N/C (losed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifica		Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date			Chief Eng	QC Inspector
							1		
							1		
				V					
								ł I	



W/O:		WORK ORDER CHANGES								,
DATE	STEP	PRO	CEDURE CH	EDURE CHANGE			Date	Qty	Approval Chief Eng /	Approval QC Inspector
									Prod Mgr	QC mapector
								l		
						į				
					Ē	:				
		PAR #:	Fault Category: NCR: Yes No DQA:				Date:			
		esolution:	Disposition:			QA: N/C Closed:			Date:	
NCR:	:	1	WORK OR	DER NON-CONFORM	MANCE	(NCR)			
DATE	STEP	Description of NC			ection B	verifica			Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Section	C	Chief Eng	QC Inspector
1										
								-		
					• •					
			1				,		ļ	1



W/O:		WORK ORDER CHANGES								•
DATE STEP PRO			CEDURE CH	EDURE CHANGE By Date			Date	Qty	Approval Chief Eng /	Approval QC Inspector
									Prod Mgr	QO mapecios
					!					
		The second secon								
									•	
Part No:		PAR #:	Fault Category: NCR: Yes No DQA:				lo DQA:			
Resolution:			Disposit	Disposition:			sed:	Date:		
NCR:	* !	1	WORK OR	DER NON-CONFORMA	ANCE (N	ICR)	. • •		,	
DATE	STEP	Description of NC Section A	Corrective Action Section			Verificat		on	on Approval	
			Initial Chief Eng	Action Description Chief Eng		gn & Date	Section C		Chief Eng	QC Inspector
	·									
	!								!	
				·						
		,					1			



W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE By Date						ety	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							,					
				·								
								I				
Part No: PAR #:		Fault Cat	_ Fault Category: N			NCR: Yes No DQA:			Date:			
Resolution:		Dispositi	Disposition: QA: N/C Closed:					Date:				
NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC				verificati			Approval	Approval		
			Chief Eng	Chief Eng		Date	Section	19	Chief Eng	QC Inspector		
		,							İ			
								1				
	:											
		esolution:V	Dispositi	OER NON-CONFORMA Corrective Action Section Action Description	QA: NOE (I	(C Clo NCR)	sed:	ıtibn	Date:			